

Carrier 19C 1200 ton Centrifugal Chiller Repair Case Study



Facility:

Class "A" High Rise

Repair Parameters:

Inlet guide vanes were seized

Repair Challenges:

No room for rigging and had to custom build a gantry to rig

Repair Rigging & Tools: Custom

Repair Time / Constraints / Opportunities:

Machines have to be repaired in place because they are located on the 36th floor



ThermaServe Mechanical Systems Services

www.thermaserve.com

T (904) 260-8002 * F (904) 260-8004 * sales@thermaserve.com

FL#CMC057091 * GA#CN209367

