

# Carrier 23XL Screw Chiller Repair Case Study



## Facility:

Low Rise Office Building

## Repair Parameters:

Replaced failed bearings, when OEM recommended complete unit replacement

## Repair Challenges:

Many tools were custom due to uncommon repair


## Repair Rigging & Tools:

Made custom tools and rigs for this unit

## Repair Time / Constraints /

## Opportunities:

We worked around the clock in shifts on a weekend because it was the building's only chiller.



ThermaServe Mechanical Systems Services

[www.thermaserve.com](http://www.thermaserve.com)

T (904) 260-8002 \* F (904) 260-8004 \* [sales@thermaserve.com](mailto:sales@thermaserve.com)

FL#CMC057091 \* GA#CN209367

