

Air Handling Unit Replacement Case Study



Facility:

Multi Story Nursing Home

Repair Parameters:

Replace existing air handling unit
On 3rd Floor

Repair Challenges:



ASHRAE Code requires new AHU's to be more efficient making them larger. The existing AHU was already in a small space.

Repair Rigging & Tools:

The new unit had to be broken down to the smallest components and re-assembled in the small space and we added a service access panel.

Repair Time / Constraints / Opportunities:

We worked with the customer for an uneventful on-time replacement



ThermaServe Mechanical Systems Services

www.thermaserve.com

T (904) 260-8002 * F (904) 260-8004 * sales@thermaserve.com

FL#CMC057091 * GA#CN209367

