

Carrier 19XL Chiller Repairs & Pump Replacement Case Study



Mechanical Systems Services

Facility:

United States Post Office

Repair Parameters:

Replace 2 chill water pumps and various chiller repairs

Repair Challenges:

Discovered need to replace high speed thrust bearings during chiller breakdown.

Repair Rigging & Tools:

We used the manufacturers written disassembly and re-assembly procedures including using precision measuring tools to compare to published values.

Repair Time / Constraints / Opportunities:

In addition to the on-time repairs we made. We also replaced the chill water butterfly and check valves



ThermaServe Mechanical Systems Services

www.thermaserve.com

T (904) 260-8002 * F (904) 260-8004 * sales@thermaserve.com

FL#CMC057091 * GA#CN209367

