

Carrier 19XR Centrifugal Chiller Repair Case Study



Facility:

High Rise Hotel

Repair Parameters:

Mechanical failure in high speed assembly

Repair Challenges:

Called to help another mechanical company to complete the repair


Repair Rigging & Tools:

No special requirements

Repair Time / Constraints /

Opportunities:

Able to help out another company with our technical support capabilities



ThermaServe Mechanical Systems Services

www.thermaserve.com

T (904) 260-8002 * F (904) 260-8004 * sales@thermaserve.com

FL#CMC057091 * GA#CN209367

