

Trane CVHF Centrifugal Chiller Cold Condenser Water Modernization Case Study



Facility:

911 Central Office Telephone Hub Building for the Southeast

Repair Parameters:

Correct low pressure (as a result of cold condenser water) refrigerant start up problem

Repair Challenges:



Modify Trane Chiller and select the appropriate controls to automate the process.

Repair Rigging & Tools:

No special tools or rigging

Repair Time / Constraints / Opportunities:

Made Trane chiller more reliable and efficient.



ThermaServe Mechanical Systems Services

www.thermaserve.com

T (904) 260-8002 * F (904) 260-8004 * sales@thermaserve.com

FL#CMC057091 * GA#CN209367

