

Centrifugal Chiller Replacement Case Study



Mechanical Systems Services

Facility:

Mid Rise Office Building

Repair Parameters:

Replace Centrifugal Chiller and two large air handlers

Repair Challenges:

Weekend *ONLY* job with a breakdown of old & installation of new

Repair Rigging & Tools:

Multiple crane picks

Repair Time / Constraints / Opportunities:

Only had one weekend to perform replacements. We worked around the clock in shifts to have the system running by Monday morning at 8am.



ThermaServe Mechanical Systems Services

www.thermaserve.com

T (904) 260-8002 * F (904) 260-8004 * sales@thermaserve.com

FL#CMC057091 * GA#CN209367

