

# Trane CVHF Centrifugal Chiller Overhaul Case Study



Mechanical Systems Services

## Facility:

Municipal Chiller plant servicing a major hospital

## Repair Parameters:

Replaced a failed bearing

## Repair Challenges:


Special rigging required

## Repair Rigging & Tools:

Some individual components weighed nearly 3 tons

## Repair Time / Constraints / Opportunities:

Made another on-time repair



ThermaServe Mechanical Systems Services

[www.thermaserve.com](http://www.thermaserve.com)

T (904) 260-8002 \* F (904) 260-8004 \* [sales@thermaserve.com](mailto:sales@thermaserve.com)

FL#CMC057091 \* GA#CN209367

